

SPEDIZIONI E SERVIZI INTERNAZIONALI

E-MAIL: andrea@cuttica.com

INTERNATIONAL FORWARDING

PH. (+39.010) 8605431

WEB SITE: <http://www.cuttica.com>

VIA CANTORE 8H (TORRECANTORE)

FAX (+39.010) 8605411

16149 GENOVA (ITALY)

Vehicle Description:

Inspection Date **5/20/2008**

Full VIN: 1XAPF4315CM827832

Mileage: 26572

Transmission Type: Automatic

Year: 82

Make: Excalibur

Model: Phantom

Engine Cylinders:8

Engine Lifters: 5.7

Engine Type: Gas

Inspection Area: Overall Rating:

Body	Excellent
Glass	Good
Wipers	Good
Tires & Wheels	Excellent
Interior Items	Good
Gauges	Excellent
Audio System	Good
Carpet & Upholstery	Good
Trunk	Good
Electrical System	Excellent
Under Hood	Good
Road Test	Good
Additional Inspection Points	Excellent



EXTERIOR

BODY

OVERALL RATING: EXCELLENT

Details:

Front	OK	Right front	OK
Right doors	OK	Right rear	OK
Rear	OK	Left rear	OK
Left doors	OK	Left front	OK
Hood	OK	Roof	OK
Bumpers	OK	Trim	OK
Overall Condition of Paint	Excellent		

GLASS

OVERALL RATING: GOOD

Details:

Windshield	OK	Right front window	OK
Right rear window	OK	Rear window	OK
Left rear window	OK	Left front window	OK

WIPERS

OVERALL RATING: **GOOD**

Details:

Front wipers	OK	Front wiper blades	OK
Front windshield washer	OK		

Comments on Exterior:

The pin stripe on the right front fender is missing in spots. There is a tear in the removable hard top at the left rear corner. Between the chrome pipes on the right front fender there is two small bumps in the paint. The windshield has some fogging around the edges; this can be seen in the picture of the VIN. There is a tiny chip on the rear edge of the passenger door.

TIRES AND WHEELS

OVERALL RATING: **EXCELLENT**

Details:

Condition of tires	Excellent	Condition of wheels	Excellent
--------------------	-----------	---------------------	-----------

Comments on Tires and Wheels:

The tires look new.

INTERIOR

TRUNK

OVERALL RATING: **GOOD**

Details:

Spare tire	OK	Carpeting	OK
Tools	OK	Jack	OK

ELECTRICAL SYSTEM

OVERALL RATING: **EXCELLENT**

Details:

Headlights	OK	Turn signals	OK
Taillights	OK	Electric windows	OK
Brake lights	OK	Electric seats	OK
Parking lights	OK		

Comments on Electrical System:

OK

UNDER HOOD

OVERALL RATING: **GOOD**

Details:

Oil leaks	NO	Exhaust leaks	NO
Exhaust smoke	YES		

INTERIOR ITEMS

OVERALL RATING: **GOOD**

Details:

Glove box	OK	Head rests	OK
A/C cooling performance	OK	Door panels	OK
Heater operation	OK	Dash pad	OK
Hood release	OK	Vanity mirrors	Not Reported
Cigarette lighter	OK		

GAUGES

OVERALL RATING: **EXCELLENT**

Details:

Speedometer	OK	Oil pressure	OK
Tachometer	OK	Amp meter	OK
Temperature	OK		

AUDIO SYSTEM

OVERALL RATING: GOOD

Details:

Radio	OK
-------	----

CARPET AND UPHOLSTERY

OVERALL RATING: GOOD

Details:

Front seats	OK	Rear seats	OK
Headliner	OK	Front carpeting	OK
Rear carpeting	OK		

Comments on Interior:

The interior has some black smudges and the driver seat back needs repair. The headliner is sagging on the right rear side. The inside passenger door has a chip in the paint.

ROAD TEST

ROAD TEST

OVERALL RATING: GOOD

Details:

Brake system - noise, vibration, effort	OK	Steering effort - drifting right or left	OK
Suspension - performance, noise, rough road test	OK	Transmission shift quality, smoothness, effort, slippage	OK
Idle	OK	Engine operating temperature	OK
Engine noise	OK	Transmission/Transaxle noise	OK
Acceleration	OK	CV joint/Drive axle noise	Not Reported
Horn	OK	Parking brake operation	OK
Wind noise	OK	Engine performance	OK
Starting	OK		

Comments on Road Test:

Some blue smoke came from the exhaust when the engine was first started. The smoke cleared after about one minute. The car ran and shifted ok. No unusual noise was heard.

ADDITIONAL INSPECTION POINTS

OVERALL RATING: EXCELLENT

Details:

Door locks	OK	Door handles	OK
Gas door	OK	Gas cap	OK
Grille	OK	Fog lamps	OK
Evidence of smoke odor	OK		

Comments on Additional Inspection Points:

OK







